

Vancouver Public Tennis Courts Structure Report

Central courts

	<p>Brewers Surface: asphalt Painted: yes, worn away Status: Cracks, root invasion, and drainage issues. Needs re-surfacing due to ball hockey use.</p> <p style="text-align: right;">Rating: 4 & Type 4 # of courts: 2</p>
	<p>Clark Surface: asphalt Painted: 2 yes, 2 no Status: There are two individually fenced-in courts on the hillside along 14th Ave. The fences are too close to the playing area to accommodate other than beginner practice. “Wrack and ruin” describes current condition. The 2 courts at 14th and Maddams (pictured) were painted by users several years ago. Lines have been painted more recently by Park Board. There are cracks by the nets.</p> <p style="text-align: right;">Rating: 3 & Type 4 # of courts: 1, 1, and 2</p>
	<p>Eburne Surface: quick dry Painted: painted Status: The “quick dry” surface is wearing away and become very slick year round.</p> <p style="text-align: right;">Rating: 5 & Type 5 # of courts: 4</p>
	<p>MacDonald Surface: asphalt Painted: yes, faded Status: Some cracking, decent shape. Sand comes onto courts from the playground.</p> <p style="text-align: right;">Rating: 3 & Type 4 # of courts: 3</p>
	<p>Memorial South Surface: asphalt Painted: no Status: Extreme moss growth. Needs re-surfacing. Small root invasion on the west side.</p> <p style="text-align: right;">Rating: 5 & Type 5 # of courts: 3</p>
	<p>Moberly Surface: asphalt Painted: no Status: Some cracking, grass growing out of cracks. Needs maintenance and repair.</p> <p style="text-align: right;">Rating: 3 & Type 4 # of courts: 4</p>
	<p>Oak Park Surface: quick dry Painted: yes Status: Extreme moss growth. Unsafe to play on. Needs re-surfacing. 1 block from Marpole Community Centre, could be good for programming.</p> <p style="text-align: right;">Rating: 5 & Type 5 # of courts: 2</p>