

Vancouver Public Tennis Courts Structure Report

West Side Public Courts

	<p>Almond Park Surface: quick dry pebbles Rating: 5 & Type 5 Painted: no, worn-off # of courts: 2 Status: Northwest side has cracking</p>
	<p>Arbutus Park (McKechnie) Surface: asphalt Rating: 3 & Type 4 Painted: no # of courts: 2 Status: North side has considerable root penetration</p>
	<p>Elm Park Surface: quick dry pebbles Rating: 5 & Type 5 Painted: no # of courts: 2 Status: Nice spot. Courts not that bad,</p>
	<p>Granville Park Surface: asphalt Rating: 3 & Type 4 Painted: no # of courts: 4 Status: Full court twin cracks from north to south on the east side. Nearby trees drop leaves and seed onto the courts. A janitor's broom comes in handy in spring and fall.</p>
	<p>Heather Park Surface: quick dry pebbles Rating: 5 & Type 5 Painted: no # of courts: 4 Status: Net posts are tilted and rusted. Nets are in poor condition. Surface needs painting. Cracks are minimal at the back of the courts. High usage courts</p>
	<p>Jericho Beach Park Surface: asphalt Rating: 2 & Type 4 Painted: no # of courts: 5 Status: Generally good courts. No major cracking. Would be ideal for lights, as there are no nearby residences.</p>
	<p>Kitsilano Beach Surface: asphalt Rating: 3 & Type 4 Painted: 5 yes, 5 no # of courts: 10 + practise wall Status: Cracking across the northern 5 courts. Some cracking on the southern 5. These courts are very popular. They need maintenance and repair. Overhanging bushes and trees put debris on the courts now and then. You may want to bring a broom.</p>